



Dolna 17, Warsaw, Poland 00-773 Tel: +48 226 0 227 03 Email: editorial_office@rsglobal.pl

JOURNAL	World Science		
p-ISSN	2413-1032		
e-ISSN	2414-6404		
PUBLISHER	RS Global Sp. z O.O., Poland		

ARTICLE TITLE	DIESEL ENGINE FUEL AND OIL CONTAMINATION IN THE AGRICULTURE SECTOR OF MONGOLIA		
AUTHOR(S)	Erdenesaikhan Oyunsurtal, Ulziibaatar Tserendorj		
ARTICLE INFO	Erdenesaikhan Oyunsurtal, Ulziibaatar Tserendorj. (2022) Diesel Engine Fuel and Oil Contamination in the Agriculture Sector of Mongolia. World Science. 3(75). doi: 10.31435/rsglobal_ws/30042022/7806		
DOI	https://doi.org/10.31435/rsglobal_ws/30042022/7806		
RECEIVED	03 March 2022		
ACCEPTED	21 April 2022		
PUBLISHED	25 April 2022		
LICENSE	This work is licensed under a Creative Commons Attribution 4.0 International License.		

© The author(s) 2022. This publication is an open access article.

ENGINEERING SCIENCES

DIESEL ENGINE FUEL AND OIL CONTAMINATION IN THE AGRICULTURE SECTOR OF MONGOLIA

Erdenesaikhan Oyunsurtal, Lecturer, School of engineering technology, Mongolian University of Life Sciences, Ulaanbaatar, Mongolia, ORCID ID: https://orcid.org/0000-0002-7913-7557 Ulziibaatar Tserendorj, Ph.D., Associate Professor, School of engineering technology, Mongolian University of Life Science, Ulaanbaatar, Mongolia

DOI: https://doi.org/10.31435/rsglobal_ws/30042022/7806

ARTICLE INFO

ABSTRACT

Received: 03 March 2022 Accepted: 21 April 2022 Published: 25 April 2022	The study was conducted to determine the amount of contamination such as soot and silicon iron of engine oil and fuel contamination of tractors of Mongolia's agricultural sector. According this research, tractors were randomly selected for field testing during spring's sowing and summer and
EYWORDS Diesel engine, fuel, oil, ontamination.	autumn harrowing time, and fuel and oil samples were taken from them with a special vacuum suction according relevant instructions and the amount of contamination was determined in accredited laboratory of Tecenomics Mongolia LLC. According to the test results, fuel contamination increases exponentially and oil contamination increases polynomial, those results depending on the type of agricultural works, and period of the work in the field of the tractors.

Citation: Erdenesaikhan Oyunsurtal, Ulziibaatar Tserendorj. (2022) Diesel Engine Fuel and Oil Contamination in the Agriculture Sector of Mongolia. *World Science*. 3(75). doi: 10.31435/rsglobal_ws/30042022/7806

Copyright: © 2022 **Erdenesaikhan Oyunsurtal, Ulziibaatar Tserendorj.** This is an open-access article distributed under the terms of the **Creative Commons Attribution License (CC BY)**. The use, distribution or reproduction in other forums is permitted, provided the original author(s) or licensor are credited and that the original publication in this journal is cited, in accordance with accepted academic practice. No use, distribution or reproduction is permitted which does not comply with these terms.

Introduction. When performing field, dust in the air mainly reaches the contact surface of the parts through the engine air filter and fuel and oil, moreover it can intensify their friction and wear. Researchers who studied about tribological indicators of engine oil contamination, they have found that soot, silicon, and iron increase the wear rate of engine parts [1, 2, 3]. The one of the main method which to protect the engine from contamination is that to optimize the frequency of maintenance of air, fuel and oil filters and to perform the services in accordance with the technology at all times. According to a study by scientists on fuel contamination, Dr. B. Purevdorj has studied how engine fuel contamination in Mongolia affects the wear and tear of feed system components, especially fuel pump plunger pairs. According to a study by scientists on fuel contamination, Dr. B. Purevdorj has studied how engine fuel contamination in Mongolia affects the wear and tear of feed system components, especially fuel pump plunger pairs and he took the and dust sample from fuel tanks and he determined fuel contamination levels [4]. According to the research of foreign researchers V.S. Loskutov and L.A. Emelyanov, the amount of contamination in the fuel tank of a tractor depends on the type of the performed work and the seasons, moreover, it has been found that the amount of contamination in the tractor tank increases by 2...3 times when transporting diesel fuel and refueling in dusty conditions [5, 6]. In addition, engine contamination are depreciating engine parts, reducing the operational resources, moreover it affects the normal operation of fuel, oil and air filters, thereby increasing fuel consumption and it reduces some technical parameters such as engine power and efficiency.

Testing methodology and instruments. Totally, 12 tractors were randomly selected and tested in the field and their fuel and oil samples were taken and analyzed in a laboratory of Tecenomics Mongol LLC. The analysis determined the amount of soot, silicon, and iron in the engine

oil, as well as the fuel contamination of each of the tractor's fuel tanks, fuel tank truck, and company fuel storage tanks.

Conditions and requirements for field testing of tractors and the methodology of oil sampling from the engine:

1. Tractors have to stop, and turn off the engine, open the tank lid within 20 minutes after the dust has been down, insert a special vacuum suction tube and take a sample of 200 ml from medium level of the fuel tank.

2. Taken same sized samples from the fuel tank truck and the company fuel tank.

3. Sampling of engine oil should be carried out under normal thermal regime (80...90°C) and 20 minutes after turn off the heated engine. Take a 200 ml sample from the middle oil level by inserting a special vacuum suction tube through the hole in the oil level check valve.

4. For each test, we noted the year of manufacture of the tractor, the type of performed work, and total worked hours.

Results. According to the methodology, fuel samples were taken from each of the 12 brands of tractors such as T-150-3, JD1204-4, Challenger, JD804, Б-1221, JD6920, T-150-4, JD1204-3, T-150-Д, JD1204-3, JD804-3, and JD6930 tractors with 4 repetitions during spring sowing, summer and autumn harrowing time, and defined the average amount of fuel contamination in the fuel bank. Accumulated contaminants in the warehouse and during fuel transportation were sampled three times at a time. Table 1 show the results which determined of the contamination that can occur during refueling in the field.

	Tractor fuel contamination, %				
	In the spring sowing	In the Summer	In the autumn		
Fuel samples	time	harrowing time	harrowing time		
point taken	(till 80 moto.hour)	(till 80160 moto.hour)	(till 160240 moto.hour)		
	Between May 5 and	Between June 20 and	Between July 25 and		
	May 28 July 5 August		August 6		
Fuel contamination in					
tractor tanks /increased		0.427292			
contamination in	0.236458		0.621875		
warehouses and fuel tank					
trucks /					
Fuel contamination in	0.06	0.07	0.08		
warehouse	0.00	0.07			
Contamination of fuel	0.07	0.08	0.09		
tank truck	0.07	0.08			
Contamination during		0.190833	0.351042		
refueling a tractor in the	0.156458				
field					

Table 1. Tractor fuel contamination

The results of the fuel analysis (Table 1) show that the amount of contaminants in the fuel tank increases as the tractor's operating time increases. The reason for this contamination is the dust that enters the tank from the ambient air along with the fuel while refueling the tractor 1...2 times a day. For example, according the research, during the 240-hour operation of a tractor field, when refueling it is contaminate by 0.156% in spring sowing, 0.191% in summer and 0.351% in autumn. Figure 1 shows how the increase in fuel contamination in the tank depends on the number of hours worked by the tractor for each type of work performed. Figure 1 shows how the increase in fuel contamination in the tank depends on the number of hours worked by the tractor for each type of work performed.






Fig. 1. The amount of fuel contamination depends on the type of performed work and the number of worked hours

For each type of tillage, the contamination of the tractor tank was y=0.0025x+0.11 in spring sowing, in summer was y=0.0024x+0.305 and in autumn was y=0.0024x+0.5, and according this equations it is increasing linearly. Figure 2 shows the geometric size of the mechanical mixture of low, medium, and highly contaminated fuels taken from a tractor bank, fuel tank truck, and farm warehouse using a microscope (Lab-Kits MB-YYS-300) 140 times more.




Fig. 2. Geometric dimensions of fuel contamination

When the mechanical mixture in the fuel is magnified 140 times more, the geometry dimention of the mixture increases as the contamination increases. This can contaminate the fuel filter and reduce its permeability, which moreover it adversely affects in the basic engine parameters. Figure 3 shows the regularity of fuel contamination in the tractor tank.




Fig.3. The relationship between annual amount of tractor fuel contamination and the type of the work

The average level of fuel contamination in the tractor bank is close to that of spring sowing and summer fallow, but it has increased sharply in autumn fallow time (Fig. 3). It is releted the land is moist during spring sowing and during the summer season, there is have a rain and less dust, however, during the autumn processing period, the land is arid because of the rainfall is less and high in plant dust.

Samples of engine oil of 12 tractors selected according to the research methodology were included in the laboratory analysis. The contaminant elements in engine oil are shown in Table 2.

№ Тракторын марк	Manufactured date	Moto. hour	Contamination			
			Soot (Soot)	Silicon (Si)	Iron (Fe)	
	марк	uate		35Abs/cm	24mg/kg	57 mg/kg
1	T-150-3	2008	2781	9	33.5	27
2	JD1204-4	2008	2975	13.8	40.8	35.8
3	Challenger	2011	794	8.1	14	35.7
4	JD804	2010	575	6.8	10.9	32.8
5	B-1221	2009	2903	10.2	38.6	33.6
6	JD6920	2009	5873	35.8	50.7	101.8
7	T-150-4	2007	2523	8.93	31.7	30.8
8	JD1204	2010	1084	8.57	21.5	38.6
9	T-150-D	2008	3512	18.6	46.1	51.3
10	JD1204-3	2008	1735	8.86	26.4	34.2
11	JD804-3	2008	1246	8.78	24.3	36.5
12	JD6930	2007	6995	57.81	84.2	201

Table 2. Contamination of tractor engine oil

According to laboratory tests, the amount of soot and silicon in tractor engine oil tends to increase as the engine life increases. The results table shows that the silicon contamination exceeds the standard limits, which confirms that the tractor engine operates in relatively dusty conditions.

Figure 4 shows how the amount of oil contaminant elements in a tractor engine depends on the service life.




Fig.4. Correlation between tractor engine life and oil contamination

As the silicon content of the engine oil increases the content of metallic elements increases by the polymer correlation. It is due to the contamination of the engine oil with silicon dust, thus it is intensifying the wear of the main contact parts of the engine, and then it is become the one of the cause of the formation of metallurgy. Therefore, it is important to regularly clean the air filter element of the tractor engine and there have to improve the design of the air purification system. **Discussions.** Researcher V.S. Bogdanov was found that added by water and mechanical impurities to engine oil, the friction force on lubricating parts of engine increased by 9...22%, its temperature by 9...11%, and wear by 33...50% [7]. James A. Addison and William M. Neidelman have identified the causes of diesel engine oil contamination and wear mode, and the types and causes of contamination. The minimum thickness of the oil layer to reduce the friction of the engine contact parts shall be up to $20 \mu m$, but the size of small particles of the contamination the oil from the outside were the same sized with minimum thickness of the oil layer [8].

The research of scientists V.S. Loskutov and L.A. Emelyanov, contamination during refueling was determined in one working day in winter and summer time, but we studied fuel contamination in spring, summer and autumn every 20 motor hours and determined the annual growth trend [5, 6]. Scientist N.Zolboo (Ph.D) determined that the number of engine failures increases as fuel contamination increases [9]. V.S. Bogdanov, James A. Addison, and William M. Neidelman also found that the amount of mechanical impurities in the oil increased engine wear and tear, but we determined the relationship between the increase in silicon, metal, and soot in the engine oil as the tractor's operating time increased.

Conclusions.

1. Tractor fuel contamination was 1.8 times higher during summer tillage than during spring sowing, and 2.63 times higher during autumn fallow tillage processing.

2. When the sample is filtered in the laboratory and the contamination is magnified 140 times more by using microscope, the size was increasing depending on the type of field work. The amount of tractor fuel contamination was 0.08% in the spring sowing time, but the contamination was increased till 0.84% at the end of autumn.

3. In order to reduce fuel contamination, cleaning the tractor's fuel tank at the end of each field work phase is the basis for ensuring that the tractor runs smoothly, maintains the technical condition of the engine, and reduces operating costs.

4. In order to reduce fuel contamination, cleaning the tractor's fuel tank at the end of each field work is the basis for ensuring that the tractor runs smoothly, maintains the technical condition of the engine, and reduces operating costs.

5. Silica contamination in engine oil which to enter by airborne dust is highly dependent on the height of the air filter tube and the type of work to be performed. The main reason for the high content of silicon in the tractor engine through the air filter from the outside is due to the dusty environment and moreover the work which to disturb the soil.

6. In the case of Mongolia, we estimate that the annual level of fuel contamination is 40% higher than that determined by the Russian Scientist L.A. Emelyanov.

7. The research in this area will be required because of the fuel and oil contamination can affect their filter permeability, engine fuel shortages, increasing the mechanical resistance of fuel and oil pumps, decreasing basic engine parameters, and increasing fuel consumption.

REFERENCES

- 1. B.A. Vzorov., A.V. Adamovich., A.G. Arabian., and others. Tractor diesel engines. Directory. Moscow "Mechanical Engineering". 1981.
- 2. I.B. Gurvich., P.E. Syrkin., V.I. Chumak. Operational reliability of automotive engines. M-Transfort.: 1994.
- 3. O. Gantulga's doctoral dissertation on "Determination of machine wear by spectral methods". Ulaanbaatar. 2015.
- 4. B. Purevdorj. Influence of some operating factors on the wear of the fuel pump plunger pair. / Doctoral dissertation / Ulaanbaatar: 2001.
- 5. L.A.Emelyanov. Filtration of diesel fuel. Moscow. Leningrad. Mashgiz, 1962.
- 6. V.S. Loskutov. Improving fuel purity in the power supply system of diesel engines of agricultural machines Abstract of dissertation ... Ph.D. Moscow. MGAU. 1999.
- 7. V.S. Bogdanov. Methods and means of ensuring the purity of fuel and lubricants in agriculture. Abstract of the dissertation dtn... Moscow. 2013.
- 8. James A. Addison, William M. Needelman. Diesel engine lubricant contamination and wear. Pall Corporation. Glen Gove. 1988.
- Zolboo. N, Khulan. B, Ulziibaatar. Ts. (2018). The study of influencing factors on working capability of "Ageo sisu power" engine utilized for crop production in Mongolia. Mongolian Journal of Agricultural Sciences, Vol 25 No 3.